Dresbach Township 2018 ROAD REVIEW

4/20/2018 @9:00am Dresbach Township

ATTENDEES: Pat Burns, Tuan Bute, Dave McCann and Travis

Zenke

Old Mill Road .403 miles

Culvert suggested repair/replace. Suggested a turn around by extending culvert?

Dip/Sink hole by Baeders

Mulder Road .409 miles

Cracks-Seal coat 1-2 years

Boat Ramp

OK-Seal

Secluded Road .124 miles

Gravely at end. State kind of maintains

Knoll Drive .031 miles

Drive way

Crab Apply Drive .038 miles

Drive way

Dresbach Drive .036 miles

Drive way

Husman Drive .042 miles

Drive way damages by garage

Freman Drive .043 miles

Drive way

Township Hall Drive .041 miles

Drive way

School Drive .033 miles

Drive way

Morning Sun Drive .040 miles

Drive way

Dickson Road .143 miles

Cracked-Seal 1-2 years

Wass Valley Drive .373 miles

Gravel on sides needs ?? Low spot Wellendorf and Amble

Old Hickory Road .315 miles

Culvert by Wellndorf needs work. Should rock by Underhills

Old Hickory Lane ??? (Not on County Road sheet) is this

supposed to be Old Hickory Road??

Shoulder Ditch clean out rocks

Oak Hill Lane ??? (Not on County Road Sheet)

Oak Hill Road ??? (Not on County Road Sheet)

Veterans Road .401 miles

Shoulder work were needed, Crack sealing, Hole by turn around

Queens Cove Drive .209 miles

Shoulder up edges breaking, ditches clean up, should work could use rock, crack sealing done

Queens Cove Circle .686 miles

Crack Sealing done

Al Moore Drive .185 miles

Ditch clean trim brush. Needs rock.

Valley View Road .238 miles

From speed sign, plow to gravel to turn around. Little wash out southside need gravel. Shoulder road

Lanes Valley Road .149 miles (Upper portion/NEW)

Gravel Road-Seal coating-granite

Buehler Road .526 miles

Gravel-no seal coat. Culvert ends. Need to be fixed. 18" Safety apron-Dig out add on. Check for need for gravel and grading

Burns Valley Road 2.208 miles

Replace on culvert (La Crescent line) inspect culverts from Burns home to La Crescent line. Place culvert markers on three culverts. Line, NWT Valley, Medds long hill? Provide drainage by Burns home and seal coat remainder. Fix seap hole by Pat's. Fence line past Pat's need culvert in and needs markers.

Roads not addressed: